



Progress Report for 2005

Boston & Maine 3713

LACKAWANNA AND WYOMING VALLEY CHAPTER NRHS

May 3, 2005

Progress Report for 2005

Boston & Maine 3713


Work continues on the 3713


The following pictures show work done on the locomotive in 2005 :

1. Much work was done to replace the many, many staybolts.
2. Work on inside of firebox and flue sheets progressed.



Inside the Firebox





Flue Sheets



Another view of the 3713

(Photos courtesy of Ken Ganz)



Veiw of locomotive showing staybolts



**This view shows staybolts being replaced
(These photos courtesy of Ed Kaspriske)**

